


## ADLER Ferrocryl

41150 ff



### Product description

High-quality water-based anti-rust basecoat and topcoat with micaceous iron ore. No additional primer required; Due to the drop-inhibited, thixotrope formulation, thick coats are possible. Excellent anti-rust effect; excellent resistance to weathering. Easy to use.

### Fields of application

Galvanised tin roofs (minimum pitch 5°) as well as steel constructions exposed to extreme weathering.  
For micaceous iron ore effect coats for outdoor and indoor application.

### Application

Coating (acrylic brush), rolling, spraying (min. nozzle size 2 mm)

### Surface preparation

#### New coat:

#### **Iron and steel:**

Wash off oil and grease residues with ADLER degreasant. Rinse with clean water.

#### **Zinc, aluminium:**

Slightly sand with grinding fleece and ADLER degreasant (surface must be matt). Rinse with clean water.

#### Redecoration coat:

Remove dirt, rust as well as loose coats. Coat severe residual rust spots generously with ADLER Ferroblock 1x. Slightly grind bonded old coats.

### Primer

Apply ADLER Ferrocryl 1x

### Topcoat

Generously apply ADLER Ferrocryl 2x  
Total dry coat thickness: min. 150 µm

### Drying time (20°C)

At least 6 hours  
It is imperative that you avoid exposure to water such as rain or dew too early!

### Application and object temperature

Not below + 10 °C  
High air humidity and/or low temperatures tend to delay drying

### Thinner

Water; delivery form: ready for application.

Continued

ADLER Ferrocryl 41150 ff

**Working equipment**

Clean with water immediately after use. Remove dried-on residue with ADLER Abbeizer (*paint remover*).

**Yield value** (per coat)

approx. 8 m<sup>2</sup>/l

**Packaging**

0.75 l, 2.5 l, 10 l

**Storage**

Cool but frost-free

**Shelf life**

At least 3 years in original, sealed containers

**Colours**

Platinum (quality 07) 41150

E 20 base for tinting 41156

Colours can be mixed with the ADLER colour mixing system.

**Safety information**

**Please pay attention to the safety information sheet!**

Also when processing low-emission products, conventional protective measures must be adhered to.

PACHE SARL